

PROBLEM	CAUSE	REMEDY
Chlorine Odour	Chloramines	Adjust pH with EASY-UP or EASY-DOWN.
		Add SHOCK, LITE-SHOCK or SHOXITE.
Black Algae Spots	Insufficient chlorine	Adjust pH with EASY-UP or EASY-DOWN.
or Mustard Algae	or bromine	Add 5 to 10 times the normal addition of SHOCK.
		Then add MBA-60 or 4LG.
Green or	Insufficient chlorine	Adjust pH with EASY-UP or EASY-DOWN.
Brown Algae	or bromine	Add 3 to 5 times the normal addition of SHOCK.
		Then add MBA-60 or 4LG.
Cloudy Water	High pH	Test and adjust the pH with EASY-DOWN.
	Early algae formation	Add SHOCK, LITE-SHOCK or SHOXITE.
	Poor Filtration	Backwash and check filter.
		Then add POLISH PLUS pool water clarifier.
Colored Water	Low Total Alkalinity	Add MSR to prevent staining.
	•	Test and adjust Total Alkalinity with BUFFER
	Low pH	Test and adjust pH with EASY-UP.
Corrosion of	Low Total Alkalinity	Add MSR to prevent staining.
Metal Parts		Test and adjust Total Alkalinity with BUFFER
	Low pH	Test and adjust pH with EASY-UP.
	Low Hardness	Test and adjust Hardness with MOR-CAL.
Eye irritation and	pH imbalance or	Adjust pH with EASY-UP or EASY-DOWN.
Skin Irritation		
	Chloramines	SHOCK-treat with SHOCK, LITE-SHOCK or SHOXITE.
	High Bathing Load	Add SHOCK, LITE-SHOCK or SHOXITE immediately.
Bromine Consumption		
	High Temperature	Add SHOCK, LITE-SHOCK or SHOXITE immediately.
	Hoovy Deinfall	Charle stabilizer level
Cools Farmer Harr	Heavy Rainfall	Check stabilizer level.
Scale Formation	High Mineral Content	Adjust water balance. To prevent further scaling add SHEILD.
Ctaining	and High pH	Control staining with MCP. Take complete dealer for testing
Stairiing	Low pn	Control staining with MSR. Take sample to dealer for testing.
	Low Total Alkalinity	Control staining with MSR. Take sample to dealer for testing
	LOW TOtal Alkalifility	Control staining with Mort. Take sample to dealer for testing.
	High Metal Content	Control staining with MSR. Take sample to dealer for testing
	g.r motar oomon	Take sumple to dealer for testing.
	High pH	Balance water. Add SHIELD
Staining	Low pH  Low Total Alkalinity  High Metal Content	Control staining with MSR. Take sample to dealer for testing.  Control staining with MSR. Take sample to dealer for testing.  Control staining with MSR. Take sample to dealer for testing.